


USAARL Report No. 93-27


AD-A270 946



**Analysis of Injury Severity  
Caused by Flight Motor Overpressure  
of the Javelin Antiarmor Missile**

By

James E. Bruckart



Impact, Tolerance, and Protection Division

July 1993

93-24703



93 10 18 001

Approved for public release; distribution unlimited.

**United States Army Aeromedical Research Laboratory  
Fort Rucker, Alabama 36362-5292**

## Notice

### Qualified requesters

Qualified requesters may obtain copies from the Defense Technical Information Center (DTIC), Cameron Station, Alexandria, Virginia 22314. Orders will be expedited if placed through the librarian or other person designated to request documents from DTIC.

### Change of address

Organizations receiving reports from the U.S. Army Aeromedical Research Laboratory on automatic mailing lists should confirm correct address when corresponding about laboratory reports.


### Disposition

Destroy this document when it is no longer needed. Do not return it to the originator.

### Disclaimer

The views, opinions, and/or findings contained in this report are those of the author(s) and should not be construed as an official Department of the Army position, policy, or decision, unless so designated by other official documentation. Citation of trade names in this report does not constitute an official Department of the Army endorsement or approval of the use of such commercial items.

### Reviewed:




JOHN V. BARSON  
LTC, MC, SFS  
Director, Impact, Tolerance,  
and Protection Division

### Released for publication:



ROGER W. WILEY, O.D., Ph.D.  
Chairman, Scientific  
Review Committee



DAVID H. KARNEY  
Colonel, MC, SFS  
Commanding

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE

REPORT DOCUMENTATION PAGE				Form Approved OMB No 0704-0188		
1a REPORT SECURITY CLASSIFICATION Unclassified			1b RESTRICTIVE MARKINGS			
2a SECURITY CLASSIFICATION AUTHORITY			3 DISTRIBUTION AVAILABILITY OF REPORT Approved for public release, distribution unlimited			
2b DECLASSIFICATION/DOWNGRADING SCHEDULE						
4 PERFORMING ORGANIZATION REPORT NUMBER(S) USAARI Report No. 93-27			5 MONITORING ORGANIZATION REPORT NUMBER(S)			
6a NAME OF PERFORMING ORGANIZATION U.S. Army Aeromedical Research Laboratory		6b OFFICE SYMBOL (if applicable) SGRD-UAD-1E	7a NAME OF MONITORING ORGANIZATION U.S. Army Medical Research and Development Command			
6c ADDRESS (City, State, and ZIP Code) P.O. Box 620577 Fort Rucker, AL 36362-0577			7b ADDRESS (City, State, and ZIP Code) Fort Detrick Frederick, MD 21702-5012			
8a NAME OF FUNDING/SPONSORING ORGANIZATION		8b OFFICE SYMBOL (if applicable)	9 PROCUREMENT INSTRUMENT IDENTIFICATION NUMBER			
8c ADDRESS (City, State, and ZIP Code)			10 SOURCE OF FUNDING NUMBERS			
			PROGRAM ELEMENT NO 0602787A	PROJECT NO 3M162787A8	TASK NO. 8 AG	WORK UNIT ACCESSION NO 138
11 TITLE (Include Security Classification) Analysis of Injury Severity Caused by Flight Motor Overpressure of the Javelin Antiarmor Missile						
12 PERSONAL AUTHOR(S) James E. Bruckart						
13a TYPE OF REPORT Final		13b TIME COVERED FROM _____ TO _____		14 DATE OF REPORT (Year, Month, Day) 1993 July		
15 PAGE COUNT 14						
16 SUPPLEMENTARY NOTATION						
17 COSATI CODES			18 SUBJECT TERMS (Continue on reverse if necessary and identify by block number)			
FIELD	GROUP	SUB-GROUP	Javelin, missile, overpressure, injury, blast			
19	09					
19	06					
19 ABSTRACT (Continue on reverse if necessary and identify by block number)						
<p>The Javelin is an antiarmor missile system designed to replace the Dragon. A rare malfunction of the missile involves overpressure of the flight motor. Data on the number, mass, and velocity of large debris items were determined by simulation of the malfunction. This report reviews the severity of injuries to the gunner or assistant gunner expected from a malfunction.</p> <p>The probability of being struck by a missile fragment was calculated as 96 in 100. The most severe injuries include a head or groin injury from either of the two largest debris items or an eye injury from any debris fragment. Other possible injuries include upper extremity fractures or superficial lacerations. Specific steps to reduce the hazard and improve personal protection will reduce the severity of injuries.</p>						
20 DISTRIBUTION/AVAILABILITY OF ABSTRACT <input checked="" type="checkbox"/> UNCLASSIFIED/UNLIMITED <input type="checkbox"/> SAME AS RPT <input type="checkbox"/> DTIC USERS			21 ABSTRACT SECURITY CLASSIFICATION Unclassified			
22a NAME OF RESPONSIBLE INDIVIDUAL Chief, Scientific Information Center			22b TELEPHONE (Include Area Code) 205-255-6907		22c OFFICE SYMBOL SGRD-UAX-SI	

DD Form 1473, JUN 86

Previous editions are obsolete

SECURITY CLASSIFICATION OF THIS PAGE

Unclassified

# Table of contents

	Page
List of figures . . . . .	2
List of tables . . . . .	2
Introduction . . . . .	3
Materials and methods . . . . .	8
Results . . . . .	10
Discussion . . . . .	11
Conclusions . . . . .	13
References . . . . .	14

Accession For	
NTIS - GPO&I	<input checked="" type="checkbox"/>
NTIS - DAR	<input type="checkbox"/>
Unpublished	<input type="checkbox"/>
Publication	
By	
Distribution/	
Availability Codes	
Full Text	
Dist	Special
A-1	

### List of figures

Figure	Page
1. Javelin missile configuration . . . . .	3
2. Missile battery . . . . .	5
3. Launch motor housing . . . . .	5
4. CAS motor . . . . .	6
5. Control fin . . . . .	6
6. TVC vane . . . . .	7
7. Schematic showing standing position for gunner, assistant gunner (exact duty position not yet decided), and missile at time of malfunction . . . . .	9

### List of tables

Table	Page
1. Estimated system weights . . . . .	3
2. Rearward velocity of overpressure debris . . . . .	4
3. Calculated frontal surface area . . . . .	10
4. Probability of being struck by a specific large debris item or any large debris item . . . . .	11
5. Kinetic energy of large debris items . . . . .	11

## Introduction

The Javelin is a man-portable, shoulder-launched, antiarmor weapon system for attacking and destroying armored tank targets. It will replace the Dragon, the current antitank weapon. The Javelin system features reduced blast signature, fire and forget targeting, and twice the range of the Dragon.

The Javelin system consists of a command launch unit (CLU) and missile round. The CLU includes a sight system for surveillance, target identification, and target lockon. The missile round consists of the launch tube assembly, battery/coolant unit, and missile. The missile is shown in Figure 1. The battery/coolant unit supplies electrical power to initiate launch and cooling gas to precool the missile seeker before launch. Estimated system weights are presented in Table 1 (Texas Instruments, 1992).




Figure 1. Javelin missile configuration.

Table 1.

Estimated system weights.

Component	Weight (kg)	Weight (lbs)
Command launch unit	6.38	14.07
Launcher	4.15	9.16
Missile	11.78	25.98

The missile system is operated by a gunner and assistant gunner. When firing the missile, both soldiers will wear the Personnel Armor System for Ground Troops (PASGT) helmet, battle dress uniform (BDU), and Kevlar® protective vest. The gunner will be positioned behind the missile with his face protected by the face shield of the command launch unit. The position of the assistant gunner has not been decided.

A rare malfunction of the Javelin missile involves in-flight overpressure of the flight motor shortly after ejection of the missile from the launch tube. This malfunction produces debris that may pose a hazard to the gunner or assistant gunner. In conjunction with the Javelin test program, the malfunction was simulated in three tests by plugging the nozzle of the flight motor on a test missile. The test articles included inert launch motors and live flight motors. For each test, high-speed cameras and debris panels were placed around the missile. This generated information on the likely debris items, scatter pattern, and velocity.

The simulated malfunction produces several small debris items including pieces of circuit board and composite materials with low mass. The large debris items include the (a) missile battery, (b) launch motor housing, (c) CAS motors [4 each], (d) control fins [4 each], and (e) TVC vane [4 each]. These items are shown in Figures 2-6 and the rearward velocity from a simulated malfunction (25 January 1993) is shown in Table 2.

Table 2.

Rearward velocity of overpressure debris\*.

Debris item	Velocity (m/s)	Velocity (fps)
Missile battery	19.1	62.8
Launch motor	17.0	55.9
housing	24.0	78.6
CAS motor (#1)	18.1	59.4
CAS motor (#2)	18.1	59.4
CAS motor (#3)	17.2	56.3
Control fin (#1)	34.6	113.6
TVC vane (#1)	22.6	74.2
TVC vane (#2)		

\* Debris velocity calculated by subtracting nominal missile velocity (44 fps) from debris velocity 4 feet behind the missile in a static test.




Figure 2. Missile battery.




Figure 3. Launch motor housing.






Figure 4. CAS motor.




Figure 5. Control fin.




Figure 6. TVC vane.

The purpose of this paper is to discuss the type and severity of injuries that would occur to the gunner and assistant gunner from in-flight overpressure of the missile. The System Safety Working Group of the Javelin program office requested this information to support the hazard assessment of an overpressure malfunction, in accordance with MIL-STD 882D (Department of Defense, 1984).

### Materials and methods

#### Probability of debris strike

Javelin missile test firings showed the flight motor ignites 0.4 seconds after the missile is launched. At that time the missile was 1.5 meters above the ground, 4.6 m (15 feet) down range, and had achieved a forward velocity of 13.4 m/s (44 fps). Figure 7 shows the relative distance between the gunner, assistant gunner (possible position), and missile at the time of malfunction. The position of the assistant gunner during missile launch has not been decided, but it should not be closer to the missile than the gunner.

Malfunction simulations show only a small probability that the gunner will be struck by a piece of debris. In these tests, the launch motor and battery have gone to the right and left side of the gunner position, respectively. If the debris spreads randomly within a cone shaped area behind the missile (60 degrees wide by 60 degrees elevation), most debris items will strike the ground or miss the soldiers. The probability that a piece of debris will strike a soldier is estimated by dividing the surface area of the soldier by the surface area of the 15-foot (4.6 m) radius sphere contained within the impact cone. The probability of being struck by at least one large piece of debris is the sum of the probabilities for each single piece of debris.

The frontal surface area of a prone, kneeling (or sitting), and standing soldier was calculated for the 95th percentile male soldier using the data collected by Gordon et al. (1989). The calculated surface areas are shown in Table 3.




Figure 7. Schematic showing standing position for gunner, assistant gunner (exact duty position not yet decided), and missile at time of malfunction.

Table 3.

Calculated frontal surface area.

Position	Method	Surface area (sq cm)
Prone	Chest depth x bideloid breadth	1500
Kneeling/sitting	Chest height x bideloid breadth	7326
Standing (face to missile)	Stature x bideloid breadth	9982
Standing (side to missile)	Stature x chest depth	5234

## Calculation of debris impact energy

Debris items that strike the gunner or assistant gunner can produce injury. The impact energy for debris that strikes the body (and does not deflect off or pass through the body) is equal to the kinetic energy of the item. The kinetic energy for each debris item is half the mass times the square of the velocity.

Results

Given a homogeneous scatter of debris in the area behind the missile malfunction, the worst case probability of being struck by a large debris item is 96 in 100. The probability of being struck by debris decreases as the surface area exposed to the blast decreases. A calculated strike probability for each position is shown in Table 4. The probability of any debris strike causing injury is small.

The kinetic energy for each debris item recovered from a malfunction simulation is presented in Table 5.

Table 4.

Probability of being struck by a specific large debris item or any large debris item.

Position	Single item (N=1)	Any item (N=14)
Prone	0.010	0.144
Kneeling or sitting	0.050	0.703
Standing (face to missile)	0.068	0.958
Standing (side to missile)	0.036	0.502

Table 5.

Kinetic energy of large debris items.

Debris item	Mass (g)	Kinetic energy (J)
Missile battery	376	68.5
Launch motor housing	825	119.2
CAS motor (#1)	130	37.4
CAS motor (#2)	130	21.2
CAS motor (#3)	130	21.2
Control fin (#1)	64	9.5
TVC vane (#1)	19	11.1
TVC vane (#2)	19	4.75

### Discussion

The method used to calculate the probability of being struck by debris assumes that each fragment is randomly expelled through the strike area. Data on the actual scatter pattern for each fragment will provide a more accurate estimate of which debris items will strike the gunner or assistant gunner.

The injury produced by a projectile is related to the shape of the projectile, type of tissue struck by the projectile, and energy deposited in the tissue (Fackler, 1987; Mendelson, 1991). The kinetic energy of the projectile is a measure of the energy that must be absorbed by the tissue to stop the movement of the object. For example, the kinetic energy of a baseball thrown at 70 miles per hour is 73 J and the kinetic energy of a 55 grain bullet fired by an M-16 (988 m/s) is 945 J (Grolier, 1992; Barach, Tommlanovich, and Nowak, 1986).

The most severe credible injury that will occur with an overpressure malfunction is an eye injury. A large debris item can pierce the eye and even small fragments from a circuit board or composite casing can lacerate the cornea. The worst credible eye injury would be critical (category II) in severity. Since the gunner's face is protected by the command launch unit, only the assistant gunner is exposed to this hazard and only if he is looking at the missile when it malfunctions. This injury can be prevented by using safety devices (goggles or a face shield) to protect the assistant gunner, or with procedures or training that prevent him from looking at the missile early in flight.

The two largest items of debris (launch motor housing and missile battery) may have sufficient impact energy to cause significant injury. If the launch motor housing or battery strikes the PASGT helmet, it can transmit sufficient energy to cause a closed head injury. This injury will produce several minutes of unconsciousness and, rarely, seizures. In addition, the same items will cause significant tissue damage if they strike the unprotected groin. These are both considered critical (category II) injuries. The head injury hazard can be reduced by adding impact attenuation characteristics (such as an energy-absorbing liner) to the PASGT helmet. The groin injury could be prevented with strike protection.

Other credible injuries from these two items include deep tissue bruising and fractures if the debris strikes the unprotected hand or forearm. There will be deep bruising in the lower extremities, but fractures are unlikely. These injuries are considered marginal (category III) in severity.

The remaining debris items have less kinetic energy and are not expected to produce the closed head injury, significant groin injury, or fractures possible with the launch motor housing or missile battery. They will cause some tissue bruising and the irregular and sharp surfaces on these debris items will penetrate the BDU and cause lacerations. These injuries are considered marginal (category III) in severity.

### Conclusions

Random dispersion of debris from an overpressure malfunction poses only a small risk that the gunner or assistant gunner will be injured. The worst credible injuries include eye injury, closed head injury, and blunt trauma to the groin. Eye injuries can be reduced by adding eye protection for the assistant gunner. The head injury and groin injury hazard will be eliminated if the launch motor housing and battery can be prevented from striking the gunner or assistant gunner. Other approaches include the addition of an energy-attenuating liner in the PASGT helmet and protection of the groin. These injuries are critical (category II) in severity.

The missile launch tube and battery can cause deep tissue bruising and fractures if they strike the forearm or hands. The remaining debris items will produce bruising and superficial lacerations if they strike areas of the body protected only by the BDU. These injuries are marginal (category III) in severity.



### References

- Barach, E., Tomlanovich, M., and Nowak, R. 1986. Ballistics: A pathophysiologic examination of the wounding mechanisms of firearms: Part 1. Journal of Trauma. 26:3. 225-235.
- Department of Defense. 1984. System safety program requirements. Washington, D.C. MIL-STD-882D. March.
- Fackler, M. L. 1987. Wounds and injuries of the soft tissues. San Francisco, CA: Letterman Army Institute of Research. Institute Report 232.
- Gordon, C. A., Bradtmiller, B. Churchill, T., Clauser, C.E., McConville, J.T., Tebbetts, I., and Walker, R.A. 1989. 1988 anthropometric survey of U.S. Army personnel: methods and summary statistics. Natick, MA: Natick Research, Development, and Engineering Center. Natick/TR-89/044.
- Grolier Electronic Publishing. 1992. Grolier Multimedia Encyclopedia. Danbury, CT.
- Mendelson, J. A. 1991. The relationship between mechanisms of wounding and principles of treatment of missile wounds. Journal of Trauma. 31:9. 1181-1202.
- Texas Instruments. 1992. Technical data document for the Javelin antitank weapon system, revision D. Lewisville, TX: Texas Instruments. DT-0023D.

Initial distribution

Commander, U.S. Army Natick Research,  
Development and Engineering Center  
ATTN: SATNC-MIL (Documents  
Librarian)  
Natick, MA 01760-5040

U.S. Army Communications-Electronics  
Command  
ATTN: AMSEL-RD-ESA-D  
Fort Monmouth, NJ 07703

Commander/Director  
U.S. Army Combat Surveillance  
and Target Acquisition Lab  
ATTN: DELCS-D  
Fort Monmouth, NJ 07703-5304

Commander  
10th Medical Laboratory  
ATTN: Audiologist  
APO New York 09180

Naval Air Development Center  
Technical Information Division  
Technical Support Detachment  
Warminster, PA 18974

Commanding Officer, Naval Medical  
Research and Development Command  
National Naval Medical Center  
Bethesda, MD 20814-5044

Deputy Director, Defense Research  
and Engineering  
ATTN: Military Assistant  
for Medical and Life Sciences  
Washington, DC 20301-3080

Commander, U.S. Army Research  
Institute of Environmental Medicine  
Natick, MA 01760

Library  
Naval Submarine Medical Research Lab  
Box 900, Naval Sub Base  
Groton, CT 06349-5900

Director, U.S. Army Human  
Engineering Laboratory  
ATTN: Technical Library  
Aberdeen Proving Ground, MD 21005

Commander  
Man-Machine Integration System  
Code 602  
Naval Air Development Center  
Warminster, PA 18974

Commander  
Naval Air Development Center  
ATTN: Code 602-B (Mr. Brindle)  
Warminster, PA 18974

Commanding Officer  
Armstrong Laboratory  
Wright-Patterson  
Air Force Base, OH 45433-6573

Director  
Army Audiology and Speech Center  
Walter Reed Army Medical Center  
Washington, DC 20307-5001

Commander, U.S. Army Institute  
of Dental Research  
ATTN: Jean A. Setterstrom, Ph. D.  
Walter Reed Army Medical Center  
Washington, DC 20307-5300

Commander, U.S. Army Test  
and Evaluation Command  
ATTN: AMSTE-AD-H  
Aberdeen Proving Ground, MD 21005

Naval Air Systems Command  
Technical Air Library 950D  
Room 278, Jefferson Plaza II  
Department of the Navy  
Washington, DC 20361

Director  
U.S. Army Ballistic  
Research Laboratory  
ATTN: DRXBR-OD-ST Tech Reports  
Aberdeen Proving Ground, MD 21005

Commander  
U.S. Army Medical Research  
Institute of Chemical Defense  
ATTN: SGRD-UV-AO  
Aberdeen Proving Ground,  
MD 21010-5425

Commander, U.S. Army Medical  
Research and Development Command  
ATTN: SGRD-RMS (Ms. Madigan)  
Fort Detrick, Frederick, MD 21702-5012

Director  
Walter Reed Army Institute of Research  
Washington, DC 20307-5100

HQ DA (DASG-PSP-O)  
5109 Leesburg Pike  
Falls Church, VA 22041-3258

Harry Diamond Laboratories  
ATTN: Technical Information Branch  
2800 Powder Mill Road  
Adelphi, MD 20783-1197

U.S. Army Materiel Systems  
Analysis Agency  
ATTN: AMXSY-PA (Reports Processing)  
Aberdeen Proving Ground  
MD 21005-5071

U.S. Army Ordnance Center  
and School Library  
Simpson Hall, Building 3071  
Aberdeen Proving Ground, MD 21005

U.S. Army Environmental  
Hygiene Agency  
Building E2100  
Aberdeen Proving Ground, MD 21010

Technical Library Chemical Research  
and Development Center  
Aberdeen Proving Ground, MD  
21010-5423

Commander  
U.S. Army Medical Research  
Institute of Infectious Disease  
SGRD-UIZ-C  
Fort Detrick, Frederick, MD 21702

Director, Biological  
Sciences Division  
Office of Naval Research  
600 North Quincy Street  
Arlington, VA 22217

Commander  
U.S. Army Materiel Command  
ATTN: AMCDE-XS  
5001 Eisenhower Avenue  
Alexandria, VA 22333

Commandant  
U.S. Army Aviation  
Logistics School ATTN: ATSQ-TDN  
Fort Eustis, VA 23604

Headquarters (ATMD)  
U.S. Army Training  
and Doctrine Command  
ATTN: ATBO-M  
Fort Monroe, VA 23651

Structures Laboratory Library  
USARTL-AVSCOM  
NASA Langley Research Center  
Mail Stop 266  
Hampton, VA 23665

Naval Aerospace Medical  
Institute Library  
Building 1953, Code 03L  
Pensacola, FL 32508-5600

Command Surgeon  
HQ USCENTCOM (CCSG)  
U.S. Central Command  
MacDill Air Force Base FL 33608

Air University Library  
(AUL/LSE)  
Maxwell Air Force Base, AL 36112

U.S. Air Force Institute  
of Technology (AFIT/LDEE)  
Building 640, Area B  
Wright-Patterson  
Air Force Base, OH 45433

Henry L. Taylor  
Director, Institute of Aviation  
University of Illinois-Willard Airport  
Savoy, IL 61874

Chief, National Guard Bureau  
ATTN: NGB-ARS (COL Urbauer)  
Room 410, Park Center 4  
4501 Ford Avenue  
Alexandria, VA 22302-1451

Commander  
U.S. Army Aviation Systems Command  
ATTN: SGRD-UAX-AL (LTC Gillette)  
4300 Goodfellow Blvd., Building 105  
St. Louis, MO 63120

U.S. Army Aviation Systems Command  
Library and Information Center Branch  
ATTN: AMSAV-DIL  
4300 Goodfellow Boulevard  
St. Louis, MO 63120

Federal Aviation Administration  
Civil Aeromedical Institute  
Library AAM-400A  
P.O. Box 25082  
Oklahoma City, OK 73125

Commander  
U.S. Army Academy  
of Health Sciences  
ATTN: Library  
Fort Sam Houston, TX 78234

Commander  
U.S. Army Institute of Surgical Research  
ATTN: SGRD-USM (Jan Duke)  
Fort Sam Houston, TX 78234-6200

AAMRL/HEX  
Wright-Patterson  
Air Force Base, OH 45433

John A. Dellinger,  
Southwest Research Institute  
P. O. Box 28510  
San Antonio, TX 78284

Product Manager  
Aviation Life Support Equipment  
ATTN: AMCPM-ALSE  
4300 Goodfellow Boulevard  
St. Louis, MO 63120-1798

Commander  
U.S. Army Aviation  
Systems Command  
ATTN: AMSAV-ED  
4300 Goodfellow Boulevard  
St. Louis, MO 63120

Commanding Officer  
Naval Biodynamics Laboratory  
P.O. Box 24907  
New Orleans, LA 70189-0407

Assistant Commandant  
U.S. Army Field Artillery School  
ATTN: Morris Swott Technical Library  
Fort Sill, OK 73503-0312

Commander  
U.S. Army Health Services Command  
ATTN: HSOP-SO  
Fort Sam Houston, TX 78234-6000

U.S. Army Dugway Proving Ground  
Technical Library, Building 5330  
Dugway, UT 84022

U.S. Army Yuma Proving Ground  
Technical Library  
Yuma, AZ 85364

AFFTC Technical Library  
6510 TW/TSTL  
Edwards Air Force Base,  
CA 93523-5000

Commander  
Code 3431  
Naval Weapons Center  
China Lake, CA 93555

Aeromechanics Laboratory  
U.S. Army Research and Technical Labs  
Ames Research Center, M/S 215-1  
Moffett Field, CA 94035

Sixth U.S. Army  
ATTN: SMA  
Presidio of San Francisco, CA 94129

Commander  
U.S. Army Aeromedical Center  
Fort Rucker, AL 36362

U.S. Air Force School  
of Aerospace Medicine  
Strughold Aeromedical Library Technical  
Reports Section (TSKD)  
Brooks Air Force Base, TX 78235-5301

Dr. Diane Damos  
Department of Human Factors  
ISSM, USC  
Los Angeles, CA 90089-0021

U.S. Army White Sands  
Missile Range  
ATTN: STEWS-IM-ST  
White Sands Missile Range, NM 88002

U.S. Army Aviation Engineering  
Flight Activity  
ATTN: SAVTE-M (Tech Lib) Stop 217  
Edwards Air Force Base, CA 93523-5000

Ms. Sandra G. Hart  
Ames Research Center  
MS 262-3  
Moffett Field, CA 94035

Commander, Letterman Army Institute  
of Research  
ATTN: Medical Research Library  
Presidio of San Francisco, CA 94129

Commander  
U.S. Army Medical Materiel  
Development Activity  
Fort Detrick, Frederick, MD 21702-5009

Commander  
U.S. Army Aviation Center  
Directorate of Combat Developments  
Building 507  
Fort Rucker, AL 36362

U. S. Army Research Institute  
Aviation R&D Activity  
ATTN: PERI-IR  
Fort Rucker, AL 36362

Commander  
U.S. Army Safety Center  
Fort Rucker, AL 36362

U.S. Army Aircraft Development  
Test Activity  
ATTN: STEBG-MP-P  
Cairns Army Air Field  
Fort Rucker, AL 36362

Commander U.S. Army Medical Research  
and Development Command  
ATTN: SGRD-PLC (COL Schnakenberg)  
Fort Detrick, Frederick, MD 21702

MAJ John Wilson  
TRADOC Aviation LO  
Embassy of the United States  
APO New York 09777

Netherlands Army Liaison Office  
Building 602  
Fort Rucker, AL 36362

British Army Liaison Office  
Building 602  
Fort Rucker, AL 36362

Italian Army Liaison Office  
Building 602  
Fort Rucker, AL 36362

Directorate of Training Development  
Building 502  
Fort Rucker, AL 36362

Chief  
USAHEL/USAAVNC Field Office  
P. O. Box 716  
Fort Rucker, AL 36362-5349

Commander U.S. Army Aviation Center  
and Fort Rucker  
ATTN: ATZQ-CG  
Fort Rucker, AL 36362

Chief  
Test & Evaluation Coordinating Board  
Cairns Army Air Field  
Fort Rucker, AL 36362

MAJ Terry Newman  
Canadian Army Liaison Office  
Building 602  
Fort Rucker, AL 36362

German Army Liaison Office  
Building 602  
Fort Rucker, AL 36362

LTC Patrice Cottebrune  
French Army Liaison Office  
USAAVNC (Building 602)  
Fort Rucker, AL 36362-5021

Australian Army Liaison Office  
Building 602  
Fort Rucker, AL 36362

Dr. Garrison Rapmund  
6 Burning Tree Court  
Bethesda, MD 20817

Commandant, Royal Air Force  
Institute of Aviation Medicine  
Farnborough Hampshire GU14 6SZ UK

Commander  
U.S. Army Biomedical Research  
and Development Laboratory  
ATTN: SGRD-UBZ-I  
Fort Detrick, Frederick, MD 21702

Defense Technical Information  
Cameron Station, Building 5  
Alexandra, VA 22304-6145

Commander, U.S. Army Foreign Science  
and Technology Center  
AIFRTA (Davis)  
220 7th Street, NE  
Charlottesville, VA 22901-5396

Director,  
Applied Technology Laboratory  
USARTL-AVSCOM  
ATTN: Library, Building 401  
Fort Eustis, VA 23604

Commander, U.S. Air Force  
Development Test Center  
101 West D Avenue, Suite 117  
Eglin Air Force Base, FL 32542-5495

Commander, U.S. Army Missile  
Command  
Redstone Scientific Information Center  
ATTN: AMSMI-RD-CS-R  
/ILL Documents  
Redstone Arsenal, AL 35898

Dr. H. Dix Christensen  
Bio-Medical Science Building, Room 753  
Post Office Box 26901  
Oklahoma City, OK 73190

Director  
Army Personnel Research Establishment  
Farnborough, Hants GU14 6SZ UK

U.S. Army Research and Technology  
Laboratories (AVSCOM)  
Propulsion Laboratory MS 302-2  
NASA Lewis Research Center  
Cleveland, OH 44135

Col. Otto Schramm Filho  
c/o Brazilian Army Commission  
Office-CEBW  
4632 Wisconsin Avenue NW  
Washington, DC 20016

Dr. Eugene S. Channing  
7985 Schooner Court  
Frederick, MD 21701-3273

LTC Gaylord Lindsey (5)  
USAMRDC Liaison at Academy  
of Health Sciences  
ATTN: HSHA-ZAC-F  
Fort Sam Houston, TX 78234

Aviation Medicine Clinic  
TMC #22, SAAF  
Fort Bragg, NC 28305

Dr. A. Kornfield, President  
Biosearch Company  
3016 Revere Road  
Drexel Hill, PA 29026

NVEOD  
AMSEI -RD-ASID  
(Attn: Trang Bui)  
Fort Belvoir, VA 22060

CA Av Med  
HQ DAAC  
Middle Wallop  
Stockbridge Hants S020 8DY UK

Commander and Director  
USAE Waterways Experiment Station  
ATTN: CEWES-IM-MI-R  
Alfrieda S. Clark, CD Dept.  
3909 Halls Ferry Road  
Vicksburg, MS 39180-6199

Mr. Peter Seib  
Human Engineering Crew Station  
Box 266  
Westland Helicopters Limited  
Yeovil, Somerset BA202YB UK

Dr. Christine Schlichting  
Behavioral Sciences Department  
Box 900, NAVUBASE NLON  
Groton, CT 06349-5900

COL C. Fred Tyner  
U.S. Army Medical Research  
& Development Command  
SGRD-ZB  
Fort Detrick, Frederick, MD 21702-5012

COL John F. Glenn  
U.S. Army Medical Research  
& Development Command  
SGRD-ZC  
Fort Detrick, Frederick, MD 21702-5012